



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



New Mexico State University  
Fire Safety Reporting [18] HEOA  
Reporting Date: January 1, 2019 to December 31, 2019

---

*NOTE: All fire drills reported below are supervised, meet International Fire Code Chapter 4 Emergency Planning and Preparedness, and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.*

---

#### **I. On-campus student housing facilities, description of the facilities and description of fire safety system.**

##### **Residence Halls**

###### **Garcia Hall (1715 International Mall)**

Garcia Hall is a three-story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2019
- Fire Drill: 1 on 09/12/2019

No fires reported. Information is in section **II Fire Statistics**.

###### **Piñon Hall (1780 East University Avenue)**

Piñon Hall is a three-story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2019



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



- Fire Drill: 1 on 09/04/2019

No fires reported. Information is in section [II Fire Statistics](#).

#### **Rhodes-Garrett-Hamiel (RGH) (2715-2735 Jordan Road)**

RGH is a three-story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2019
- Fire Drill: 1 on 09/10/2019

No fires reported. Information is in section [II Fire Statistics](#).

### **Campus Apartments**

#### **Cervantes Village**

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

No fire reported. Information is in section [II Fire Statistics](#).

#### **Chamisa Village I & II (1735 Stewart Street)**

Chamisa Village is a complex made-up of three-story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

#### Chamisa Village I

- Fire Drill: 1 on 02/11/2019
- Fire Drill: 1 on 09/10/2019

#### Chamisa Village II

- Fire Drill: 1 on 02/11/2019
- Fire Drill: 1 on 09/10/2019

No fire reported. Information is in section [II Fire Statistics](#).

#### Vista Del Monte

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).

### Family Housing

#### Tom Fort and Sutherland Villages

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



#### Greek Housing

##### Chi Omega (1700 East University Avenue)

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2019
- Fire Drill: 1 on 09/04/2019

No fires reported. Information is in section II [Fire Statistics](#).

##### Delta Zeta (1600 East University Avenue)

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2019
- Fire Drill: 1 on 09/04/2019

No fires reported. Information is in section II [Fire Statistics](#).

##### Zeta Tau Alpha (1699 East University Avenue)

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



- Fire Drill: 1 on 02/12/2019
- Fire Drill: 1 on 09/04/2019

No fires reported. Information is in section II [Fire Statistics](#).

### Academic Buildings

#### Spring 2019

#### Engineering Complex II - John Whitlock Hernandez Hall (3035 South Espina Street)

Engineering Complex II - John Whitlock Hernandez Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Engineering Complex II - John Whitlock Hernandez Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/04/2019

No fires reported. Information is in section II [Fire Statistics](#).

#### Engineering Complex III - Ed & Harold Foreman Hall (1060 Frenger Mall)

Engineering Complex III - Ed & Harold Foreman Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Engineering Complex III - Ed & Harold Foreman Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/04/2019

One fire reported. Information is in section II [Fire Statistics](#).

#### Jett Hall Building & Jett Annex (1040 S. Horseshoe)



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



Jett Hall Building & Jett Annex is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classroom areas.

Fire Protection: Jett Hall Building & Jett Annex is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/04/2019

No fires reported. Information is in section II [Fire Statistics](#).

#### **Undergraduate Learning Center (2702 McFie Circle)**

Undergraduate Learning Center is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classroom areas.

Fire Protection: Undergraduate Learning Center is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/05/2019

No fires reported. Information is in section II [Fire Statistics](#).

#### **William B. Conroy Honors Center (2475 S. Espina Street)**

William B. Conroy Honors Center is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classroom areas.

Fire Protection: William B. Conroy Honors Center is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/05/2019

No fires reported. Information is in section II [Fire Statistics](#).



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



#### Fall 2019

##### **American Indian Student Center (3015 Andrew Wall Place)**

American Indian Student Center is a single-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: American Indian Student Center is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system and fire pump. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system and fire pump are inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/03/2019

No fires reported. Information is in section **II Fire Statistics**.

##### **Communication Science Building (1405 International Mall)**

Communication Science Building is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: Communication Science Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/09/2019

No fires reported. Information is in section **II Fire Statistics**.

##### **O'Donnell Hall Building (1220 Stewart Street)**

O'Donnell Hall Building is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories and classroom areas.

Fire Protection: O'Donnell Hall Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/03/2019

No fires reported. Information is in section II [Fire Statistics](#).

#### **Rentfrow Gym Building (3165 Williams Avenue)**

Rentfrow Gym Building is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Rentfrow Gym Building is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/03/2019

No fires reported. Information is in section II [Fire Statistics](#).

#### **Skeen Hall (945 East College Avenue)**

Skeen Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, conference rooms, classrooms, lecture rooms, laboratories, and work station areas.

Fire Protection: Skeen Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/09/2019

No fires reported. Information is in section II [Fire Statistics](#).



# NMSU Fire Department 2020 Annual Fire Safety Report Clery Act Requirement



## Non-Academic Buildings

### Fires in Non-Academic Buildings

One fire reported at Corbett Center – Taos Cafeteria kitchen area, 1600 International Mall. Information is in section II [Fire Statistics](#).

### Fires in Academic Buildings

One fire reported at Science Hall, 1290 Frenger Mall. Information is in section II [Fire Statistics](#).

One fire reported at Engineering Complex III - Ed & Harold Foreman Hall, 1060 Frenger Mall. Information is in section II [Fire Statistics](#).

## Fatality or Casualty Fires

None reported.

## Arson Fires

None reported or identified.



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



## II. Fire Statistics

### 2019 Digital Fire Log

#### FIRES INSIDE STRUCTURES

DATE	ADDRESS	INCIDENT
4/22/2019	Science Hall 1290 Frenger Mall	118 - Trash or rubbish fire, contained
08/28/2019	Corbett Center - Taos Cafeteria kitchen area 1600 International Mall	111 - Building fire
9/30/2019	Engineering Complex III - Ed & Harold Foreman Hall 1060 Frenger Mall	111 - Building fire

#### FIRES OUTSIDE STRUCTURES

DATE	ADDRESS	INCIDENT
3/3/2019	406 MCARTHUR DR University Park NM 88003 GREGG ST / WELLS ST	154 - Dumpster or other outside trash receptacle fire
4/19/2019	Geothermal DR University Park NM 88003 Water Pump Rd	142 - Brush or brush-and-grass mixture fire
5/25/2019	Union University Park NM 88003 College	142 - Brush or brush-and-grass mixture fire
5/25/2019	Union University Park NM 88003 College	142 - Brush or brush-and-grass mixture fire
6/10/2019	Early College High School 3600 Arrowhead # 1 University Park NM 88003	162 - Outside equipment fire
9/28/2019	3205 Arrowhead DR University Park NM 88003 Wells ST	118 - Trash or rubbish fire, contained
10/8/2019	University Park NM 88003 Locust	131 - Passenger vehicle fire



# NMSU Fire Department

## 2020 Annual Fire Safety Report

### Clery Act Requirement



### III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <https://fire.nmsu.edu/fire-prevention-guidelines/>

### IV. 2018 Annual Security Report, New Mexico State University Police Department

Found online at: <https://www.nmsupolice.com/annual-reports/>

### V. 2018 Annual Reports, New Mexico State University Fire Department

Found online at: <https://fire.nmsu.edu/annual-reports/>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.